

HERITAGE ASSESSMENT
APPENDIX THREE: HISTORIC PHOTOGRAPHS

Leaside Business Centre
43-45 Gillender Street
London E14 6RN

June 2019

Ray Rogers
AA Dipl RIBA MRTPI IHBC
Heritage & Urban Design

Delcia Keate
BSc Grad Dipl Cons AA IHBC



Fig 1 Bromley Hall from the north-west, showing the 'Manor House' (right) and intervening cottages. 1957 watercolour copied from illustration in *The Survey of London Vol. I Bromley-by-Bow* (1900). THLHA



Fig 2 Bromley Hall c1890. THLHA



Fig 3 The 'Manor House' c1912. THLHA



Fig 4 Manor Cottages c1900. This terrace of c1830 stood on the site of Poplar Library; the south flank wall of the 'Manor House' is to the left. THLHA



Fig 5 Poplar Library showing the pair of villas which stood to the south. Early 20th century photograph. THLHA



Fig 6 Poplar Library, probably taken in the 1930s. THLHA



Fig 7 Rear (south) elevation of Bromley Hall, taken prior to the addition of the late 1920s south extension when Bromley Hall was occupied by the Royal College of St Katharine. THLHA



Fig 8 Rear elevation of Bromley Hall following bomb damage on 20 October 1940. THLHA



Fig 9 Bomb crater in the garden of Bromley Hall. THLHA



Fig 10 View looking north 1956. THLHA



Fig 11 View of Tyler's garage, built on the site of the Manor House, and Poplar Library. 1957. THLHA



Fig 12 Bromley Hall looking east, showing the inter-war factory shed which stands to the north (left) and Tyler's garage (right). 1968. THLHA